

1954 Corvette: Service Bulletin: Vacuum Modulator Spring Throttle Valve Inner Spring

Subject: Vacuum Modulator Spring Throttle Valve Inner Spring

Model and Year: 1954 Powerglide Transmission

Source: Chevrolet Technical Service Bulletin

Bulletin No: DR - 165

Section: VII

Date: January 29, 1954

TO: ALL CHEVROLET DEALERS

1954 Powerglide Transmissions built after Serial Number C106D will have the same up and down shifting characteristics as the 1953 Unit.

The Vacuum Modulator Spring used in the 1954 Powerglide Transmission has been replaced by 1953 spring and Throttle Valve Inner Spring is omitted.

SERVICE

In cases where an objectionable severe downshift or "clunk" is encountered in transmissions built prior to above serial number, the 1953 Vacuum Modulator Spring should be installed and the Throttle Valve Inner Spring removed.

PARTS

Description : Vacuum Modulator Spring (1953 and late 1954)

Part No : 3691669

Early 1954 Vacuum Modulator Spring is identified by an orange stripe.

There is no identification mark on the 1953 spring which is shorter than the 1954 early spring.

E.L. Harrig
Manager, Service and Mechanical Department

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1954-corvette-service-bulletin-vacuum-modulator-spring-throttle-valve-inner-spring-1126.html>