

1970 Corvette: Service News: Front Fender Side Louver Replacement

Subject: Front Fender Side Louver Replacement

Model and Year: 1970 Corvette

Source: Chevrolet Service News

Page Number: 2

Date: Section 1A, March 1970, Volume 42, Number 3

1. Reach up beneath the front fender lower edge and remove a locknut threaded on a stud fastened to the bottom of the louver.
2. From the outside, remove (2) screws driven through the upper edge of the louver.
3. Gently lift the louver up and off the fender.
4. Reverse Steps 1-3 for installation.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1970-corvette-service-news-front-fender-side-louver-replacement-1191.html>