

# 1970 Corvette: Service News: Front Fender Side Louver Replacement

---

**Subject:** Front Fender Side Louver Replacement


**Model and Year:** 1970 Corvette

**Source:** Chevrolet Service News

**Page Number:** 2

**Date:** Section 1A, March 1970, Volume 42, Number 3

1. Reach up beneath the front fender lower edge and remove a locknut threaded on a stud fastened to the bottom of the louver.
2. From the outside, remove (2) screws driven through the upper edge of the louver.
3. Gently lift the louver up and off the fender.
4. Reverse Steps 1-3 for installation.



**Figure 1—Fender Side Louver**

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1970-corvette-service-news-front-fender-side-louver-replacement-1191.html>