

2014 Corvette: GM TechLink: Compass Always Shows North

Subject: Compass Always Shows North

Model and Year: 2014 Buick Regal, LaCrosse, Cadillac ATS, Cadillac CTS VIN A, Cadillac SRX, Cadillac XTS, Corvette, Impala, Silverado 1500 and Sierra 1500 models

Source: GM TechLink

Page Number: NA

Date: December 22, 2015

The compass on the radio display may always show North (N) regardless of vehicle direction on some 2014 Regal, LaCrosse, ATS, CTS VIN A, SRX, XTS, Corvette, Impala, Silverado 1500 and Sierra 1500 models. This condition affects the following radios: RPO IO5 (Regal, LaCrosse, CTS VIN A, XTS, Impala, Silverado, Sierra), RPO RAO without UY4 – Navigation (SRX, Corvette); and RPO UA3 without UY4 – Navigation (ATS).

The compass direction when the navigation icon is selected should indicate the vehicle direction. Reprogram the radio with the latest calibrations using TIS2Wev to address this condition with the compass.

- Thanks to Ryan Dorland

Custom Fields

- **Source:** GM TechLink

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-corvette-gm-techlink-compass-always-shows-north-1259.html>