

2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 13, 2016)

#16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 13, 2016)

Subject: Loss of Radio Controls and/or HVAC Controls

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Corvette | 2014 | 2016 | | | All | All |

| | |
|-----------------------------------|--|
| <i>Involved Region or Country</i> | North America and all N.A.Export Regions |
| <i>Condition</i> | Some customers may comment on a loss of function with the Radio/HVAC Interface Control Module (ICS) after ignition 'on' cycle. The condition will exhibit intermittent characteristics, where the loss of function will discontinue after an additional ignition cycle. |
| <i>Cause</i> | This may be caused by incorrect software/utility file level. |

Correction

If you encounter a vehicle with the above concern, reprogram the radio control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2016-corvette-service-bulletin-16-na-188-loss-of-radio-controls-and-or-hvac-controls-jun-13-2016-1278.html>