

# 2014 - 2016 Corvette: Service Bulletin: #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

## #16-NA-188: Loss of Radio Controls and/or HVAC Controls - (Jun 29, 2016)

**Subject:** Loss of Radio Controls and/or HVAC Controls

---

Brand:	Model:	Model Year:	VIN:	Engine:	Transmission:
		from to	from to		
Chevrolet	Corvette	2014 to 2016		All	All

***Involved Region or Country***

North America and all N.A.Export Regions

***Condition***

Some customers may comment on a loss of function with the Radio/HVAC Interface Control Module (ICS) after ignition 'on' cycle.

The condition will exhibit intermittent characteristics, where the loss of function will discontinue after an additional ignition cycle.

***Cause***

This may be caused by incorrect software/utility file level.

**Correction**

If you encounter a vehicle with the above concern, reprogram the radio

control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2014-2016-corvette-service-bulletin-16-na-188-loss-of-radio-controls-and-or-hvac-controls-jun-29-2016-1287.html>