

## 2016 - 2017 Corvette: Service Bulletin: #PIP5447B: P3400 setting with 8 speed only - (Apr 4, 2017)

### #PIP5447B: P3400 setting with 8 speed only - (Apr 4, 2017)

<b>Subject:</b>		P3400 setting with 8 speed only					
Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016 - 2017		All	All	6.2L LT1	8 Speed
Chevrolet	Corvette	2016 - 2017		All	All	6.2L LT1	8 Speed

<i>Involved Region or Country</i>	North America
<i>Additional RPO/s:</i>	N/A
<i>Condition</i>	The vehicles listed in the PI may have a concern of a DTC P3400 setting
<i>Cause</i>	Unknown at this time.

#### Correction

Follow SI diagnostics for DTC P3400 to be sure this is not a false concern.

Document the findings and repair as needed per the service

procedure.

Try to capture a GDS2 session for review.

If the concern was not duplicated or repaired following SI, call GM Technical Assistance to set up a case and provide results from SI diagnostics.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2016-2017-corvette-service-bulletin-pip5447b-p3400-setting-with-8-speed-only-apr-4-2017-1352.html>