

# 2020 Corvette: Service Bulletin: #20-NA-214: Information on Front Side Door Window Intermittently Auto Reverses When Going Up or Down - (Oct 30, 2020)

## #20-NA-214: Information on Front Side Door Window Intermittently Auto Reverses When Going Up or Down - (Oct 30, 2020)

**Subject:** Information on Front Side Door Window Intermittently Auto Reverses When Going Up or Down

Brand:	Model:	Model Year:	VIN:	Engine:	Transmis		
		from	to		sion:		
Chevrolet	Corvette	2020	2020	—	—	All	All

### *Involved Region or Country Condition*

North America, Saudi Arabia  
Some customers may comment that when they are operating either door glass up or down, the window may intermittently auto reverse.

### *Cause*

The cause of the condition may be that the door window may be out of adjustment.

### *Correction*

**Note:** DO NOT replace the window motor, or window regulator, without making the door window adjustment first.

Adjust the front side door window.  
Refer to *Front Side Door Window Adjustment* in SI.

## Parts Information

No parts are normally required for this repair.

*Version*

1

*Modified*

Released October 30, 2020

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2020-corvette-service-buletin-20-na-214-information-on-front-side-door-window-intermittently-auto-reverses-when-going-up-or-down-oct-30-2020-1468.html>