

Chevrolet Service Bulletin: Information on Tire Radial Force Variation (RFV)

Service Bulletin #: 00-03-10-006A

Date: June 2005

Subject: Information on Tire Radial Force Variation (RFV)

Model(s):

2006 and Prior Passenger Cars and Light Duty Trucks

2006 and Prior HUMMER H2

2006 HUMMER H3

2000 - 2005 Saturn L Series

2003 - 2006 Saturn ION

This bulletin is being revised to add additional models, model years and additional information. Please discard Corporate Bulletin Number 00-03-10-006 (Section 03 -- Suspension)

Attached below is the PDF document for this service bulletin.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/chevrolet-service-bulletin-information-on-tire-radial-force-variation-rfv-203.html>