

# 2005 - 2007 Corvette: Service Bulletin: Information on 2-3 Upshift or 3-2 Downshift Clunk Noise

**Bulletin No:** 01-07-30-042D

**Date:** May, 2006

**Subject:** Information on 2-3 Upshift or 3-2 Downshift Clunk Noise

**Models:**

2007 and Prior Passenger Cars and Light Duty Trucks

2003-2007 HUMMER H2

2006-2007 HUMMER H3

2005-2007 Saab 9-7X

with 4L60-E or 4L65-E Automatic Transmission (RPOs M30, M32)

**NOTE:** This bulletin is being revised to add the 2007 model years and include passenger cars. Please discard Corporate Bulletin Number 01-07-30-042C (Section 07 -- Transmission/Transaxle).

The complete, one page PDF file of this bulletin is linked below:

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2007-corvette-service-bulletin-information-on-2-3-upshift-or-3-2-downshift-clunk-noise-230.html>