

# 1997 - 2003 Corvette: Service Bulletin: Info - Tire Pressure Monitoring System (TPMS) Grommet/Seal Availability

**Subject:** Tire Pressure Monitoring System (TPMS) Grommet/Seal Availability

**Source:** Chevrolet Dealer Technical Service Bulletin

**Number:** 03-03-10-004 - (04/07/2003)

**Models:** 1999-2003 Chevrolet Corvette

2000-2003 Cadillac DeVille, DHS, DTS, Seville

## **Important**

**Do not replace the wheel mounted Tire Pressure Monitoring Module if the grommet requires replacement. Replace only the grommet.**

The above vehicles may include an on-wheel tire pressure monitoring module that is an integral part of the tire valve stem. This system utilizes a replaceable grommet at the wheel air valve opening. If this grommet becomes damaged or unserviceable, order GM P/N 25715243 for a replacement. **DO NOT** replace the wheel mounted Tire Pressure Monitoring Module.

**Part Number:** 25715243

**Description:** Grommet, Tire Valve

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your

vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1997-2003-corvette-service-bulletin-info-tire-pressure-monitoring-system-tpms-grommet-seal-availability-376.html>