

1997 - 2004 Corvette: Service Bulletin: Vehicle is Difficult to Fuel or Filling Station Pump Shuts Off Before Tank is Full

Service Bulletin #: 04-06-04-031 - Issued: 4/22/04

Vehicle is difficult to fuel or filling station pump shuts off before tank is full

1997 - 2004 Chevrolet Corvette

Condition: You may find that when attempting to fill your fuel tank with gas, the pump will shut down before the tank is actually full.

Cause: The condition may be caused by back pressure within the fuel filler hose. This back pressure trips the fuel nozzle prior to filling the tank, or results in a hard to fill condition.

Correction: Replace the fuel tank filler hose with P/N 10353139. This new hose has been redesigned to provide smoother flow conditions within the section.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1997-2004-corvette-service-bulletin-vehicle-is-difficult-to-fuel-or-filling-station-pump-shuts-off-before-tank-is-full-405.html>