

1984 - 1986 Corvette: Service Bulletin: Electric Outside Rear View Mirrors

Subject: Electric Outside Rear View Mirrors

Model and Year: 1984 - 1986 Corvette

Source: Chevrolet Dealer Service Bulletin

Bulletin Number: 86-176, Section 8B

Date: Oct., 1986

TO: ALL CHEVROLET DEALERS

Customer comments of inoperative outside rear view mirrors (which have been diagnosed as inoperative motors) can be repaired with new repair kits from WDDGM.

The repair kits have the rubber boots removed from the up/down, in/out jackscrews and the part numbers are as follows:

HEATED:

P/N: 10065261 - Left Side

P/N: 10065262 - Right Side

NON-HEATED:

P/N: 10065263 - Left Side

P/N: 10065264 - Right Side

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1984-1986-corvette-service-bulletin-electric-outside-rear-view-mirrors-582.html>

