

1984 Corvette: Service Bulletin: Brake Pad Hold-Down Spring Breakage

Model Year: 1984 Corvette

Subject: Brake pad Hold-Down Spring Breakage

Source: Chevrolet Dealer Service Bulletin

Bulletin Number: 84-232, Section 5 (V)

Date: January, 1985

TO: ALL CHEVROLET DEALERS

Some 1984 Corvettes may experience brake pad hold-down spring breakage. Stainless steel hold-down spring and pin kits are now available for service. The stainless steel spring kit (P/N 14091366) includes material and instructions to service either the front or rear pads. Two (2) kits are required to service the entire vehicle.

New brake pads are available with the stainless steel springs and pins to replace pads with fully worn linings. The following part numbers should be used when ordering new pad assemblies:

Front - 14091367

Rear - 14091368

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1984-corvette-service-bulletin-brake-pad-hold-down-spring-breakage-643.html>