

1991 Corvette: Service Bulletin: Potential Paint Peeling on Front Fascias

Subject: POTENTIAL PAINT PEELING ON FRONT FASCIAS

Model and Year: 1991 CORVETTE

Source: Chevrolet Service Bulletin

Bulletin Number: 91-134-10 - (11/27/1990)

TO: ALL CHEVROLET DEALERS

Condition: Some 1991 Corvettes prior to VIN M5103213 may exhibit paint peeling on front bumper fascias.

Correction: New front fascias will be made available in body color as replacement parts.

1. Call 1-800-457-VETT and provide information on V.I.N., body color and repair location.
2. Part will be shipped to repair location indicated.
3. Following the repair, return the original fascia in the carton for the replacement part.

Labor Operation Number: B 0048

Use applicable Labor Time Guide for labor hours.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1991-corvette-service-bulletin-potential-paint-peeling-on-front-fascias-652.html>