

1957 Corvette: Service Bulletin: 1957 Passenger Car and Truck Camshaft Identification

Subject: 1957 Passenger Car & Truck Camshaft Identification

Model and Year: 1957 Passenger Car & Truck

Source: Chevrolet Service Bulletin

Bulletin Number: DR #292, Section VI, April 29, 1957

TO: ALL CHEVROLET DEALERS

Charts on pages 2 and 3 of this bulletin list 1957 Passenger and Truck Camshafts used in the various engines and a means of identification by casting number.

In instances where two casting numbers are given in chart for one engine, the upper number identifies the service shaft and the other the production shaft. The service shaft is universal, fitting all models 55 thru 57.

1957 PASSENGER CAR CAMSHAFT CHART

MODELS	REG. PROD. OR RPO	ENGINE					CAMSHAFT	
		TYPE	GROSS H. P.	COMP. RATIO	VALVE LIFTER	CARBURETOR	CASTING NUMBER	SERVICE PART NO.
1500	Reg. Prod.	Blue-Flame - 140 "235" 6-cyl.	140 @ 4200 RPM	8.0-to-1	Hyd.	Single Barrel	3836386	3836483
	RPO 221	Turbofire 265 V-8	162 @ 4400	8.0-to-1	Hyd.	Two Barrel	3703906 or 3836862	*3704212
2100	RPO 223	Turbofire 283 V-8	185 @ 4600	8.5-to-1	Hyd.	Two Barrel	3732798	3733431
2400	RPO 410	Super Turbofire 283 V-8	220 @ 4800	9.5-to-1	Hyd.	Four Barrel	3732798	3733431
1500 Exc. 1508	RPO 411	Corvette 283 V-8	245 @ 5000	9.5-to-1	Hyd.	Two Four Barrel	3732798	3733431
	RPO 411 & Special Cam	Corvette 283 V-8	270 @ 6000	9.5-to-1	Mech.	Two Four Barrel	3736098	3736097
2100	RPO 578	Corvette 283 V-8	250 @ 5000	9.5-to-1	Hyd.	Fuel Injection	3732798	3733431
2400	RPO 578 & Special Cam	Corvette 283 V-8	283 @ 6200	10.5-to-1	Mech.	Fuel Injection	3736098	3736097
2900	Reg. Prod.	Corvette 283 V-8	220 @ 4800	9.5-to-1	Hyd.	Four Barrel	3732798	3733431
	RPO 469	Corvette 283 V-8	245 @ 5000	9.5-to-1	Hyd.	Two Four Barrel	3732798	3733431
	RPO 469 & Special Cam	Corvette 283 V-8	270 @ 6000	9.5-to-1	Mech.	Two Four Barrel	3736098	3736097
	RPO 579	Corvette 283 V-8	250 @ 5000	9.5-to-1	Hyd.	Fuel Injection	3732798	3733431
	RPO 579 & Special Cam	Corvette 283 V-8	283 @ 6200	10.5-to-1	Mech.	Fuel Injection	3736098	3736097

*Service Shaft - Slot in rear Journal for oil flow to Oil Gallery - used in 55 thru 57 models.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1957-corvette-service-bulletin-1957-passenger-car-and-truck-camshaft-identification-769.html>