1953 - 1958 Corvette: Service Bulletin: Fuel Filter Element Maintenance

Subject: Fuel Filter Element Maintenance

Model and Year: 1957-1958 Models - Passenger

Source: Chevrolet Service Bulletin

Bulletin Number: DR #370, Section VIm, July 18, 1958

A highly efficient fuel filter mounted near the carburetor on some 1957 and 1958 models gives the Chevrolet owners protection from foreign material and resulting carburetor problems.

This filter has a removable sediment bowl for clean-out and a replaceable element.

Filter elements should be replaced every 5,000 miles as covered in Owner's Manual Maintenance Chart to insure trouble free operation for the customer.

PARTS DATA

Description Usage	Part No
-------------------	---------

(W/Gasket) 53-58 Corvette

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin

applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

https://www.corvetteactioncenter.com/tech/knowledgebase/article/1953-1958-corvette-service-bulletin-fuel-filter-element-maintenance-777.html