

1973 Corvette: Service News: Red Idle Mixture Screw Caps

Subject: Red Idle Mixture Screw Caps

Model and Year: 1973 Corvette

Source: Chevrolet Service News

Page Number: Page 1

Date: November 1972, Volume 44, Number 11

As of July 31, 1972, the red idle mixture screw replacement cap hits will no longer be available from G.M.P.D for service.

The absence of the original caps is more than adequate identification that carburetor adjustments have been made. The discontinued service replacement cap kits are as follows:

PART NO. CARBURETOR

7043677 1 Bbl.

7043684 2 Bbl.

7042801 4 Bbl.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1973-corvette-service-news-red-idle-mixture-screw-caps-822.html>