

1955 Corvette: Service Bulletin: Hard Shifting

Less than 100 1955 Corvettes were built with the 3-speed manual transmission. This Chevrolet Technical Service Bulletin, DR #236 covers all of those Corvettes. This information is not in the 1955 Chevrolet Shop Manual.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1216>