

1974 Corvette: Product Safety Campaign: Fuel Tank Return Line Tube Fitting Leakage

1974 Corvette built within serial range number 15,309 through 18,652 had a possibility of a fuel tank return line breaking.

Subject: Product Safety Campaign No. 74C13 - Fuel Tank Return Line Tube Fitting Leakage - 1974 Corvette

Model and Year: 1974 Corvette

Source: Chevrolet Dealer Product Campaign Bulletin

Bulletin Number: 74-C-13, Section VIII

Date: March, 1974

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1241>