1963 - 1967 Corvette: Chevrolet Service News: Two-Unit Voltage Regulator Diagnosis and Adjustment

Subject: Two-Unit Voltage Regulator Diagnosis and Adjustment

Model and Year: 1963 - 1967 Corvette

Source: Chevrolet Service News

Page Number: 1

Date: June 1963, Volume 35, Number 6

This updated service information was issued late in 1963 Corvette production. The voltage regulation system was brand new for the 1963 Corvette and was used on all 1963 - 1967 Corvettes. 1963 Corvette Shop Manuals do not have this diagnosis and adjustment procedures.

| Online URL: https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1258 |
|---|
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |