

2017 Corvette: Customer Satisfaction Program: 16119 Incorrect Monroney Label

General Motors has discovered an inadvertent error in the Parts Content Information portion of the window label on certain 2017 model year Cadillac ATS and XTS, Chevrolet Camaro, Corvette, Cruze, Impala, Malibu, Silverado LD, and Sonic, and GMC Sierra LD vehicles, which displays US/Canadian Parts Content for the vehicle, and Country of Origin (COO) information for the engine and transmission on these vehicles. As a result, the label displayed incorrect parts content percentages and COO information for the engines and transmissions on these vehicles. GM will contact involved owners of the affected to notify them of the situation. This label error has no effect on the safety or operation of the vehicles.

As a result, General Motors is releasing Customer Satisfaction Program 16119 today. The total number of U.S. vehicles involved is approximately 46,000.

Replacement labels with the corrected information are being reprinted and will be mailed to involved dealers of record beginning the week of February 6, 2017.

The customer letter mailing will begin in the near future. Included with the letter will be a paper reproduction of their vehicle's Monroney label with corrected information. This facsimile is being provided for their records and no dealer action is required.

Below is the attached campaign notice.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=1323>