

2006 Corvette: Service Bulletin: Cold Tire Characteristics of GM Original Equipment Tires

Attached below is a one page PDF document detailing the cold tire characteristics that may be seen on all GM original equipment tires.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/2006-corvette-service-bulletin-cold-tire-characteristics-of-gm-original-equipment-tires-272.html>