

1984 - 1985 Corvette: Service Bulletin: Brake Pad Replacement Part Numbers

Subject: Brake Pad Replacement Part Numbers

Model and Year: 1984-1985 Corvette

Source: Chevrolet Service Bulletin

Bulletin Number: 84-225 - (11/10/1984)

A NEW BRAKE PAD MATERIAL HAS BEEN RELEASED FOR THE 1985 CORVETTE. THE NEW MATERIAL WILL BE SUPPLIED IN BRAKE PAD SERVICE KITS, P/N 14091367 FRONT AND P/N 14091368 REAR, FOR USE ON 1984 AND 1985 CORVETTES REPLACING 1984 SERVICE BRAKE PAD KITS, P/N 14067582 FRONT AND P/N 14067583 REAR. WHEN REPLACING BRAKE PADS, USE COMPLETE AXLE SETS, DO NOT MIX 1984 AND THE NEW 1985 BRAKE PADS FROM LEFT TO RIGHT SIDE OF THE VEHICLE. MIXING 1984 AND THE NEW 1985 BRAKE PADS FRONT TO REAR IS AN ACCEPTABLE REPLACEMENT PROCEDURE. VISUAL IDENTIFICATION 1984 - LINING WEAR INDICATORS ARE LOCATED IN THE CENTER OF THE OUTER PAD. 1985 - LINING WEAR INDICATORS ARE LOCATED ON THE TRAILING EDGE OF THE INNER PADS.

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=645>