

1986 Corvette: Service Bulletin: Corvette Body Repair Materials

Subject: Corvette Body Repair Materials
Model and Year: 1986 Corvette
Source: Chevrolet Dealer Service Bulletin
Bulletin Number: 86-185, Section 10
Date: Oct., 1986

TO: ALL CHEVROLET DEALERS

Comments have been received that current structural epoxies and cosmetic fillers, including P/N 1051885 epoxy released by GMWDD are unsatisfactory.

Some recommended repair/filler materials and a list of distributors are being provided.

STRUCTURAL EPOXY

A new improved material, a two-part epoxy, has been released for use as a structural adhesive. It is Fusor 320/322 and can be ordered from various distributors.

COSMETIC FILLERS

For cosmetic repairs, two fillers are recommended:

Akemi Filler7
Adtech 17

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1986-corvette-service-bulletin-corvette-body-repair-materials-659.html>