

1963 - 1964 Corvette: Service Bulletin: 3-Speed Transmission Problems

Subject: 3-Speed Transmission Problems

Model and Year: All Passenger Cars and 10-20 Series Trucks - 1963-1964

Source: Chevrolet Technical Service Bulletin

Bulletin No: TSB #1008 DR #676

Section: VII

Date: July 16, 1964

TO: ALL CHEVROLET SERVICE PERSONNEL

This Bulletin is intended to provide corrective measures for the following problems if encountered on the vehicles indicated:

- Gear clash on first and reverse shift. All subject vehicles except Corvair and Corvair 95
- Shifting difficulty - All subject vehicles except Corvair, Corvair 95 and Chevy Van
- Countergear and thrust washer installation - All subject vehicles
- Bearing noise - All subject vehicles except Corvair and Corvair 95

Detailed instructions for correcting the above conditions are covered in the attached pages.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=919>