

# 1963 Corvette: Service Bulletin: Improved Vacuum Modulator

**Subject:** Improved Vacuum Modulator  
**Model and Year:** 1963 Aluminum Powerglide  
**Source:** Chevrolet Technical Service Bulletin  
**Bulletin No:** DR #568  
**Section:** VII  
**Date:** December 17, 1962

TO: ALL CHEVROLET DEALERS

An improved vacuum modulator system has been incorporated in the 1963 Aluminum Powerglide transmission effective at start of production at Cleveland and beginning with transmission code #T911 at Toledo. Modulator parts are not interchangeable between old and new design. If service is required, replace parts must be same type as original equipment.

The old and new vacuum modulator systems are illustrated on the reverse side. Parts data is also included to enable the correct parts to be obtained in the event replacement is required.

ALL 1962 AND EARLY 1963 TOLEDO TRANSMISSIONS	ALL 1963 CLEVELAND AND 1963 TOLEDO DATE STAMPED T911 AND LATER	DESCRIPTION
3789122	3830276	Vacuum Modulator Valve
---	3830311	Vacuum Modulator Valve Plunger
3812741	3830229	Vacuum Modulator Assem.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article.php?id=957>