

1956 Corvette Service News: Corvette Transmission Control Lever Seal

Subject: Corvette Transmission Control Lever Seal

Model and Year: 1956 Corvette

Source: Chevrolet Service News

Page Number: 3

Date: September, 1956 - Volume 28 - Number 9

A new larger transmission control lever seal, Part No. 3733482, which permits more freedom of movement is currently available for 1956 Corvettes equipped with either a Powerglide or 3-speed transmission.

This seal was introduced because the replaced seal, 3728550, caused a binding condition when the shift lever was moved into the "Park" position on Powerglide models and would at times cause the shift lever to jump from "3rd" position into "Neutral" on 3-speed transmission equipped cars.

Online URL: <https://www.corvetteactioncenter.com/tech/knowledgebase/article/1956-corvette-service-news-corvette-transmission-control-lever-seal-1150.html>