2016 Corvette: Service Update - Performance Timer Missing

15814 - Service Update - Performance Timer Missing

Updated Date: Mar 17, 2016 12:25 ET

GLOBAL SAFETY FIELD INVESTIGATIONS

DCS3969

URGENT - DISTRIBUTE IMMEDIATELY

Date: March 17, 2016

Subject: 15814 - Service Update - Performance Timer Missing

Models: 2016 Chevrolet Corvette

To: All Chevrolet Dealers

General Motors is releasing Service Update 15814 today. The total number of U.S. vehicles involved is approximately 10,933. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen in the GWM system will be updated March 21, 2016. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

Online URL: <u>https://www.corvetteactioncenter.com/tech/knowledgebase/article/2016-corve</u> <u>tte-service-update-performance-timer-missing-1262.html</u>