

2015 - 2019 Corvette: Service Bulletin: Tire Replacement / Mounting Information

#PIC6084C: Tire Replacement / Mounting Information - (Mar 5, 2018)

Subject:				Tire Replacement / Mounting Information			
Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette Z06	2015 - 2019		All	All	All	All
Chevrolet	Corvette Grand Sport	2017 - 2019		All	All	All	All
Chevrolet	Corvette ZR1	2019		All	All	All	All

Supersession Statement

This PI was superseded to update Model Years. Please discard all copies of PIC6084B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some dealership technicians may have difficulty seating the beads on any of the various tires available for those vehicles reflected in the

Models section.

Recommendation/Instructions

If this issue is encountered, dealership technicians are to login to the GM Training website at <https://www.centerlearning.com/HomePage/LoginPage.asp>

This issue is addressed in the May 2015 Emerging Issues Broadcast and the video may be viewed by dealership technicians to obtain the latest information and direction on mounting these tires.

The course number for this video is 10215.05D

The segment on mounting these tires begins at the 20:24 mark and ends at the 24:20 mark.

Canadian Dealers: This video segment is viewable in the Centre of Learning. Search for the VOD titled “Low Profile Tire Bead Seating Procedures”.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2015-2019-corvette-service-bulletin-tire-replacement-mounting-information-1393.html>