

# 2020 - 2021 Corvette: Service Bulletin: #20-NA-123: Malfunction Indicator Lamp (MIL) Illuminated, DTCs U1961, U1983 Set - (Mar 8, 2021)

## #20-NA-123: Malfunction Indicator Lamp (MIL) Illuminated, DTCs U1961, U1983 Set - (Mar 8, 2021)

**Subject:** Malfunction Indicator Lamp (MIL)  
Illuminated, DTCs U1961, U1983 Set

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmi ssion:
		from	to	from	to		
Buick	Envisio n	2021	2021	—	—	—	—
Cadillac	CT4	2020					
	CT5						
	Escalad e Models	2021					
Chevrol et	Corvett e	2020					
	Suburba n	2021					
	Tahoe						
GMC	Yukon Models						

<i>Involved Region or Country</i>	North America, Middle East, GM Korea Company, Israel, Palestine
<i>Condition</i>	<p>Some customers may comment that the Malfunction Indicator Lamp (MIL) is illuminated.</p> <p>Technicians may find the following DTCs set:</p> <ul style="list-style-type: none"> <li>• U1961 - Control Module Security Hardware Internal Malfunction</li> <li>• U1983 - Serial Data Gateway Module Security Hardware Internal Malfunction</li> </ul>
<i>Cause</i>	This condition may be caused by not clearing the DTCs and also allowing a sleep cycle after programming or serial data authentication configuration.
<i>Correction</i>	Clear the DTCs and allow the vehicle to go into sleep mode.
<i>Version</i>	3
<i>Modified</i>	<p>Released June 02, 2020</p> <p>November 13, 2020 – Added the Cadillac Escalade Models, Chevrolet Suburban, Tahoe and GMC Yukon Models and Warranty Information.</p>

March 08, 2021 – Added the 2021 Buick Envision and 2021 MY to CT4, CT5 and Corvette.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2020-2021-corvette-service-bulletin-20-na-123-malfunction-indicator-lamp-mil-illuminated-dtcs-u1961-u1983-set-mar-8-2021-1494.html>