

# 2020 - 2021 Corvette: Service Bulletin: #21-NA-091: Information on Normal Rearview Camera Display Operation - Flashing Diamond - Spot - or UFO like image on Rear View Camera Display - (Apr 13, 2021)

## #21-NA-091: Information on Normal Rearview Camera Display Operation - Flashing Diamond - Spot - or UFO like image on Rear View Camera Display - (Apr 13, 2021)

**Subject:** Information on Normal Rear View  
Camera Display Operation - Flashing  
Diamond - Spot - or UFO like image  
on Rear View Camera Display

This bulletin replaces PIT5799A. Please discard PIT5799A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmi ssion:
		from	to	from	to		
Cadilla c	CT4	2020	2020	—	—	—	—
	CT5		2021				
	Escalad e						
	Escalad e ESV						
Chevrol et	Bolt EV	2020	2020				
	Corvett		2021				

e

Silverad

o 1500

Silverad

o 2500

HD/350

0HD

Tahoe

Suburba

n

<b>GMC</b>	Sierra	2020	2021
	1500		
	Sierra 2		
	500HD/		
	3500H		
	D		
	Yukon		
	Yukon		
	XL		

***Involved Region or Country***

North America, Uzbekistan, Russia, Middle East, Israel, Palestine, Chile, Colombia, Ecuador, Paraguay, Peru, Korea, Thailand, Brazil

***Additional Options (RPOs)***

Equipped with UVI, UVS or UV2

***Condition***

Some customers may comment on a flashing light present on the radio display when in Reverse and with the rear view camera on, usually is

corrected by an ignition cycle.





*Correction*

Please communicate to the customer that the rear view camera system and radio display are functioning as designed and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this bulletin.

Technicians should verify that no other conditions are present and return the vehicle to the customer.

*Version*

1

*Modified*

Released April 13, 2021

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2020-2021-corvette-service-bulletin-21-na-091-information-on-normal-rearview-camera-display-operation-flashing-diamond-spot-or-ufo-like-image-on-rear-view-camera-display-apr-13-2021-1507.html>