

2005 - 2007 Corvette: Service Bulletin: Head Up Display (HUD) Bezel Warped from High Ambient Temperature/UV Rays

Date: October 24, 2006

Bulletin #: #06-08-49-020

Subject: Head Up Display (HUD) Bezel Warped from High Ambient Temperature/UV Rays

Models: 2005-20067 Chevrolet Corvette

Condition

Some customers may comment that the bezel for the Head Up Display (HUD) is warped.

Cause

The bezel may be warping from heat and the sun's UV rays.

Correction

Replace the Head Up Display (HUD) bezel.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-2007-corvette-service-bulletin-head-up-display-hud-bezel-warped-from-high-ambient-temperature-uv-rays-325.html>