

2005+ Corvette: GM TechLink: Avoiding Scratched Headlamps

Owners should be reminded not to use an ice scraper on the headlamps of the 2005 Corvette. The exposed headlamps are covered by clear plastic lenses that have a hardcoated material applied at the supplier to resist scratching. Trying to clear snow, ice, or frost with a sharp instrument (ice scraper) could damage the hardcoat material and make the lens susceptible to scratching.

The following are some suggested methods for clearing the lens surface of snow, ice, or frost.

- water to melt the deposit
- cloth
- credit card
- rubber squeegee

- Thanks to Luke Ananian, GM TechLink, February 2005

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/2005-corvette-gm-techlink-avoiding-scratched-headlamps-363.html>

