

1985 - 1987 Corvette: Service Bulletin: Moan or Vibration with Air Conditioning Running

Source: Chevrolet Dealer Service Bulletin

Subject: Moan or Vibration with Air Conditioning Running

Model and Year: 1985 - 87 Corvette

Bulletin Number: 87-206

Section: 1B

Date: Sept., 1987

TO: ALL CHEVROLET DEALERS

Some 1985 -87 Corvettes may exhibit a moan or engine vibration when the air conditioning compressor is engage. This condition may be improved by the installation of a power steering pump rear bracket and brace kit, P/N 10077573. Installation instructions are provided in the kit.

© Copyright General Motors Corporation. All Rights Reserved

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1985-1987-corvette-service-bulletin-moan-or-vibration-with-air-conditioning-running-78.html>