

1958 Corvette: Service Bulletin: Automatic Transmission Fluid

Subject: Automatic Transmission Fluid

Model and Year: 1958 Passenger Cars and Trucks

Source: Chevrolet Service Bulletin

Bulletin Number: DR #318, Section VII

Date: October 17, 1957

TO: ALL CHEVROLET DEALERS

Automatic Transmission Fluid used in 1958 production will be dyed red. This makes identification easy and should be of considerable assistance in diagnosing engine and transmission oil leaks.

This change will enter production at all Assembly Plants as soon as existing stocks of transmission fluid are exhausted.

ELH:kv

EL Harrig
Manager, Service and Mechanical Department

General Motors bulletins are intended for use by professional technicians, not a "do-it-yourselfer". They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for

information on whether your vehicle may benefit from the information.

© Copyright General Motors Corporation. All Rights Reserved.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1958-corvette-service-bulletin-automatic-transmission-fluid-783.html>