1967 Corvette: Service News: Air Conditioning Diagnosis

Subject: Air Conditioning Diagnosis

Model and Year: 1967 Corvette **Source:** Chevrolet Service News


Page Number: Page 8

Date: July 1967 - Volume 39, Issue Number 8

The "Air Conditioning Diagnosis" chart given on page 8 will help pinpoint air conditioning malfunctions. It is applicable to all Chevrolet passenger car and truck air conditioning systems; Four Season, Comfortron, All Weather & Comfort-Car. When this checking sequence is used on the Comfortron System, it will facilitate the pinpointing of the problem areas so that they can be more specifically checked with the procedures appearing on page 1A-36 of the 1967 (Passenger Car) Chassis Service Manual.

It should also be noted here that there have been other service publications during the 1967 model year concerning air conditioning diagnosis and subsequent corrections. For ready reference a chart has been prepared giving the name, date and coverage of each publications.

DATE OF PUBLICATION	PUBLICATION	COVERAGE
December, 1966	Service News (SN-P-1)	Correction of delayed starting time in 1966 Comfortron systems.
March 6, 1967	Chevrolet Dealer Service Technical Bulletin (67-T-15)	Correction of 1967 Chevrolet or Camaro 4-Season Systems having any one of the following malfunctions 1. Low side outlet air flow 2. Windshield fogging. 3. Difficulty in maintaining a comfortable temperature. 4. Blower motor operation during fresh air venting.
May, 1967	Service News (SN-C-16)	Comfortron System Check Additions



Online URL:

https://www.corvetteactioncenter.com/tech/knowledgebase/article/1967-corvette-service-news-air-conditioning-diagnosis-845.html