

# 1959 Corvette: Service Bulletin: Decal Added to Air Cleaner to Aid Installation and Prevent Carburetor Linkage Interference

**Subject:** Decal Added to Air Cleaner to Aid Installation and Prevent Carburetor Linkage Interference

**Model and Year:** 1959 Corvette

**Source:** General Motors of Canada Service Bulletin

**Bulletin No:** NA

**Section:** Page 82

**Date:** September 15, 1959

Effective in Production on July 6th, 1959, a decal was added on the top front of the air cleaner assembly to indicate "Front" of the air cleaner and insure proper installation. This was done so that the recesses in the underpan of the air cleaner, which are provided to allow clearance for the carburetor linkage, will be properly located. If these recesses are not properly located, the carburetor rods can interfere with the underpan of the air cleaner and cause improper choke closing. Early air cleaners without decals should be rotated at installation until the carburetor linkage drops into the recesses.

Online URL:

<https://www.corvetteactioncenter.com/tech/knowledgebase/article/1959-corvette-service-bulletin-decal-added-to-air-cleaner-to-aid-installation-and-prevent-carburetor-linkage-interference-942.html>